

Telford North Water Monitoring Results

Date	September, 2024			Weather	Light clouds and a gentle breeze				Temperature range	10° - 14°c	
				Weather for Previous 24 hours	Rain - heavy in the morning				Temperature range	13° - 15°c	
Site Code	Site name	Grid reference	Test initials	Date	Time	Temperature / cel	Turbidity%	Ammonia mg/l	pH/pH units	Comments	
AP04	Apley – Duck Pond	SJ6564913146	AT	24/09/2024	09:25	13.9	3	1.00	6.6		
AP05	Apley - Bathing Pond	SJ6557513099	MH	24/09/2024	09:37	13.4	4	0.25	6.6		
DH01	Charlton Pool	SJ6465812932	AT	24/09/2024	09:55	13.4	0	0.00	6.5		
DH02	Dothill Pool (inlet)	SJ6456612626	AT	24/09/2024	10:05	15.0	0	0.10	6.7	Algal blooms throughout	
DH03	Dothill Pool (outlet)	SJ6446112720	MH	24/09/2024	10:15	15.1	2	0.10	6.7	Algal blooms throughout	
DH04	Tee Lake (inlet)	SJ6416312987	AT	24/09/2024	10:25	14.5	0	0.30	7.2	Note pH	
DH05	Tee Lake	SJ6428212989	AT	24/09/2024	10:35	15.2	1	0.10	6.7	Organic scum at edge of pool	
DH06	Canal	SJ364123312885	AT	24/09/2024	10:56	13.2	2	1.00	6.7		
DH07	Dothill Bridge	SJ6409612808	AT	24/09/2024	11:30	15.1	0	0.10	7.5	57 sec flow time	
DH08	Admaston/Wellington Bridge	SJ363944312492	AT	24/09/2024	11:42	13.4	7	0.10	7.1	22 sec flow time	
DH09	Beanhill Brook, Shawbirch	SJ363823313251	MH	24/09/2024	12:00	13.4	1	0.10	7.5	45 secs	
DH10	End of Drain	SJ363842313300	AT	24/09/2024	12:05	14.0	0	0.10	7.0	40 secs	