

# Telford North Water Monitoring Results

Date	August, 2024			Weather	Light rain and a moderate breeze				Temperature range	13° - 20°c	
				Weather for Previous 24 hours	Sunny intervals and a gentle breeze				Temperature range	13° - 21°c	
Site Code	Site name	Grid reference	Test initials	Date	Time	Temperature / cel	Turbidity/%	Ammonia mg/l	pH/pH units	Comments	
AP04	Apley – Duck Pond	SJ6564913146	MH	27/08/2024	09:30	16.6	10	2.00	6.7		
AP05	Apley - Bathing Pond	SJ6557513099	AT	27/08/2024	09:37	15.8	10	0.10	6.5		
DH01	Charlton Pool	SJ6465812932	AT	27/08/2024	09:55	15.7	7	0.75	6.9		
DH02	Dothill Pool (inlet)	SJ6456612626	AT	27/08/2024	10:08	17.5	10	0.10	7.4	Many algae threads in sample but not as bad as last month	
DH03	Dothill Pool (outlet)	SJ6446112720	MH	27/08/2024	10:17	17.2	15	0.10	7.4	Many algae threads in sample but not as bad as last month	
DH04	Tee Lake (inlet)	SJ6416312987	AT	27/08/2024	10:27	15.2	0	0.10	7.0		
DH05	Tee Lake	SJ6428212989	AT	27/08/2024	10:35	17.3	0	0.10	7.5	Slightly high pH and temp.	
DH06	Canal	SJ364123312885	MH	27/08/2024	10:45	15.6	1	1.00	7.1	High ammonia due to leaf fall	
DH07	Dothill Bridge	SJ6409612808	MH	27/08/2024	10:51	15.5	0	0.10	7.5	123 secs	
DH08	Admaston/Wellington Bridge	SJ363944312492	MH	27/08/2024	11:14	14.3	0	0.10	7.5	83secs	
DH09	Beanhill Brook, Shawbirch	SJ363823313251	AT	27/08/2024	11:35	14.4	0	0.10	7.0	Over 5 mins flow time	
DH10	End of Drain	SJ363842313300	AT	27/08/2024	11:40	14.6	0	0.10	6.9	120 secs	



