

# Telford North Water Monitoring Results

Date	August 2023			Weather	Dull with heavy showers				Temperature range	11-17 deg C	
				Weather for Previous 24 hours	Dull, overcast with little of no rain				Temperature range	11-17 deg C	
Site Code	Site name	Grid reference	Test initials	Date	Time	Temperature / cel	Turbidity/%	Ammonia mg/l	pH/pH units	Invertebrate score	Comments
AP04	Apley – Duck Pond	SJ6564913146	MH	29/08/2023	08:10	15.6	5	2.00	7.0		
AP05	Apley - Bathing Pond	SJ6557513099	MH	29/08/2023	08:20	14.7	20	0.50	6.8		
DH01	Charlton Pool	SJ6465812932	MH	29/08/2023	08:45	15.1	3	1.00	6.8		
DH02	Dothill Pool (inlet)	SJ6456612626	MH	29/08/2023	09:10	17.1	15	0.25	7.0		
DH03	Dothill Pool (outlet)	SJ6446112720	MH	29/08/2023	09:15	17.4	20	0.10	7.3		
DH04	Tee Lake (inlet)	SJ6416312987	MH	29/08/2023	09:30	15.0	0	0.10	7.5		
DH05	Tee Lake	SJ6428212989	MH	29/08/2023	09:40	17.4	10	0.10	7.0		
DH06	Canal	SJ364123312885	MH	29/08/2023	10:00	17.5	5	1.00	6.8		
DH07	Dothill Bridge	SJ6409612808	CH	29/08/2023	10:10	17.7	0	0.10	7.5		125 sec
DH08	Admaston/Wellington Bridge	SJ363944312492	CH	29/08/2023	10:25	13.7	0	0.10	7.5		39 sec
DH09	Beanhill Brook, Shawbirch	SJ363823313251	MH	29/08/2023	10:45	14.2	0	0.00	7.5	3.7	Too overgrown to time flow. Kick test done at SJ 364096 312808 on 22/08/2023
DH10	End of Drain	SJ363842313300	MH	29/08/2023	10:55	13.9	0	0.00	7.5	3.8	185 sec Kick test done at SJ364096 312808 on 22/08/2023