

Telford North Water Monitoring Results - Dothill and Shawbirch LNR

Date	March, 2024			Weather	Cloudy, light rain & gentle breeze				Temperature range	5° - 10°c	
				Weather for Previous 24 hours	Cloudy and showery				Temperature range	7° - 10°c	
Site Code	Site name	Grid reference	Test initials	Date	Time	Temperature / cel	Turbidity/%	Ammonia mg/l	pH/pH units	Comments	
AP04	Apley – Duck Pond	SJ6564913146	MH	26/03/2024	09:30	9.7	0	0.50	6.5	Pond burst its banks	
AP05	Apley - Bathing Pond	SJ6557513099	AT	26/03/2024	09:44	8.8	11	0.25	7.0	Recent work around the pool edge may have affected turbidity	
DH01	Charlton Pool	SJ6465812932	MH	26/03/2024	10:05	9.3	2	0.00	6.5		
DH02	Dothill Pool (inlet)	SJ6456612626	MH	26/03/2024	10:15	10.3	0	0.00	6.7		
DH03	Dothill Pool (outlet)	SJ6446112720	MH	26/03/2024	10:20	10.1	0	0.00	6.5		
DH04	Tee Lake (inlet)	SJ6416312987	AT	26/03/2024	10:35	10.0	10	0.00	7.0		
DH05	Tee Lake	SJ6428212989	AT	26/03/2024	10:45	10.4	0	0.00	7.0		
DH06	Canal	SJ364123312885	AT	26/03/2024	11:00	9.2	5	0.00	7.0		
DH07	Dothill Bridge	SJ6409612808	AT	26/03/2024	11:05	10.4	0	0.00	7.5	Very slow 60secs+	
DH08	Admaston/Wellington Bridge	SJ363944312492	AT	26/03/2024	11:15	8.7	1	0.10	7.0		
DH09	Beanhill Brook, Shawbirch	SJ363823313251	AT	26/03/2024	11:35	8.9	0	0.10	7.0	56 secs	
DH10	End of Drain	SJ363842313300	AT	26/03/2024	11:38	9.8	0	0.00	7.0	40 secs	

