

# Water Quality Test Results – DotHill Area

Date 31/01/2023	Weather: Dry and cloudy	Temperature range: 3-8 °C
Previous 24 hours	Weather: Dry and cloudy	Temperature range: 3-8 °C

Location	Time	Grid Ref.	Temp / °C	Turbidity / %	Ammonia / PPM	pH	Tester initials	Comments
Duckpond, Apley	11:15	SJ6564913146	5.8	15	1.00	6.7	MH	
Bathing Pool, Apley	11:25	SJ6557513099	6.6	5	0.00	6.5	MH	
Charlton Pool	14:45	SJ6465812932	6.8	5	0.00	6.5	CN	
Dothill Pool (inlet)	14:35	SJ6456612626	6.3	15	3.00	7.3	MH	Possible faecal pollution.
Dothill Pool (outlet)	14:20	SJ6446112720	6.1	10	0.25	6.8	MH	Work being done to deepen pool
Tee Lake (inlet)	14:00	SJ6416312987	8.8	20	0.00	7.3	MH	Note turbidity and temp. No evidence of faecal pollution
Tee Lake	13:59	SJ6428212989	6.8	17	0.00	8.0	CN	Work being done to deepen pool. Note pH.
Canal	13:30	SJ364123312885	6.6	0	0.00	6.8	MH	
Dothill Bridge	1:18	SJ6409612808	8.8	0	0.00	7.4	CN	69 secs Note temp and pH.
Admaston/Wellington Bridge	13:04	SJ363944312492	7.3	5	0.00	7.0	MH	29 secs
Beanhill Brook, Shawbirch	12:40	SJ363823313251	7.6	5	0.00	7.0	CN	43 secs
End of Drain	12:20	SJ363842313300	7.5	0	0.00	6.8	MH	Over 5 minutes. Blocked at bridge.



# Water Quality Test Results – Hurley Brook Area

Date 29/01/2023	Weather: Dry and sunny	Temperature range: 6-2°C
Previous 24 hours	Weather Dry and overcast	Temperature range; 7-2°C

Location	Time	Grid Ref.	Temp / °C	Turbidity / %	Ammonia / PPM	pH	Tester initials	Comments
Apley fishing lake - Inlet	11:15	SJ6457713495	6.1	0	0.25	7.0	BFC/MV	
Apley fishing lake - outlet	11:32		6.2	0	0.00	7.0	BFC/MV	Debris around outlet grill
Apley – Duck Pond	1146	SJ6566213117	6.6	0	1.00	7.0	BFC/MV	